

Solomatic II 80

- Sturzsituation
- Seilführung
- Vertikalschnitt

- Situation linteau
- Guidage par câble
- Coupe verticale

- Situazione veletta
- Funi di guida
- Sezione verticale

Ed. 06.16

solomatic II 80S_01 / 1:1

GRIESSER

